

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 1439144 NR. 29W 5CR Mer.

Sec. Cor. Corner common to Sections
31, 32, 5, and 6

Corner consists of a Iron Stake (not) in place
State condition Good

Dimensions above ground 10 inches.


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T143N R29W S6

T144N R29W S31

T144N R29W S32

T143N R29W S5

BT

BT

BT

BT

Species Birch Aspen Aspen Birch

Diameter 7" 8" 11" 6"

Bearing S74W N55W N31E S48E

Distance 33 25 90 13

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

OR Bowen

Signature

Estimate


Title. 2-5 3027

12/9/30
Date.

(Make sketch of topography near Corner.)

Mer.

T. 1434W R. 79N 5th



Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

_____ chains distant.

Give any further facts which will aid in finding this

Corner again

In surface markings found