

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Shepewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144 N* R. *R 20 W* S. Mer.

Sec. Corner common to Sections
22, 23, 6, and 5

Corner consists of a *Concrete Monument* (not) in place
State condition *from map 1890/1891*

Dimensions above ground *16* inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<i>37</i>	<i>6</i>	<i>5</i>	<i>33</i>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

144 N
229 W
333

37

Species *Aspen* _____

Diameter *10"* _____

Bearing *N 70 E* _____

Distance *118'* _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

A. L. ...

Signature.

12/10/38
Date.

Title. *Z-9* 3027

Corner again.

Corner failed Stone

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner.)

8-3027

Mer.

T. 144 N. R. 29 W.