

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 29 W 50 Mer.

Sec Corner common to Sections

17, 20, 21, and 21

Corner consists of a Metal post (not) in place

State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

17			16
	20	21	
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T144N R29W S17
----------------------

T144N R29W S20
----------------------

T144N R29W S21
----------------------

T144N R29W S16
----------------------

BT

BT

BT

BT

Species R Oak Aspen Maple White Pine

Diameter 12 11 11 12

Bearing N66W S51W S20E N12E

Distance 21 22 13 66

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

O. R. Boerner

Signature.


Estimator

Title. N-9 8-3027

11/24/30  
Date.

T. 144 N. R. 29 W

(Make sketch of topography near corner.)



Metal Location Poster is on a

Red Oak

tree 12 inches diameter, on the N.W.

side of Sec. 20 R.

from which this Corner bears N 66 W

11 chains distant.

Give any further facts which will aid in finding this Corner again.