

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*posted*

*Chipmunk* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *146N* R. *29W* *5* Mer.

*S 1/16* Corner common to Sections

*22*, *23*, and



Corner consists of a *Iron Stake* (not) in place  
State condition

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>S 1/16</i>	<i>S 1/16</i>		
<i>S 22</i>	<i>S 23</i>		

<i>BT</i>	<i>BT</i>		
-----------	-----------	--	--

*Dead* →

Species	<i>Balsam</i>	<i>Balsam</i>		
Diameter	<i>12"</i>	<i>16"</i>		
Bearing	<i>S 22 W</i>	<i>S 67 E</i>		
Distance	<i>?</i>	<i>?</i>		

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Q. R. Brewer*

Signature  
*Permitator*

*12/18/30*  
Date.

