

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

*Chippewa*  
 CHIPPENWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14N R. 29W 5th Mer.

1116 Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, 14, and 23

Corner consists of a iron pipe (not) in place

State condition good

Dimensions above ground 1.5" x 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>W 1/16</u> <u>cor</u> <u>14 &amp;</u> <u>23</u>			
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>W 1/16</u> <u>5 23</u>	<u>W 1/16</u> <u>5 14</u>		
<u>BT</u>	<u>BT</u>		

Species Maple W. Spruce

Diameter 4.4" 8"

Bearing S 35W N 12W

Distance 281ks. 271ks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

E. M. Hardy

(Signature)


C. O. P.

(Date)

(Title)

Blank lined area for notes at the top of the page.

Corner again.  
Give any further facts which will aid in finding this  
chain distant  
from which this Corner bears  
side of  
tree  
inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

P. 123

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 29 W. 5 th. Mer.

1/16 Corner common to Sections  
14, and 23



Corner consists of a Iron pipe (not) in place  
State condition good

Dimensions above ground 1.5" by 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Maple W. Spruce

Diameter 4" 6"

Bearing S35W N12W

Distance 28 lks. 23 lks.

Do you believe this to be a genuine Land Office Corner? yes.

If not, why?

Earl M. Handy

(Signature)

Chief of Party

(Date)

(Title)

.....

.....

.....

.....

.....

.....

.....


.....

.....

.....

Corner again.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree..... inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)