

U. S. Department of Agriculture
FOREST SERVICE

*Handy
posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W 5 Mer.

116 Corner common to Sections
_____, _____, and 14

Corner consists of a 1.57 PIPE (not) in place

State condition good

Dimensions above ground 1.5 x 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>SW</u>			
<u>116</u>			
<u>514</u>			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>SW</u> <u>116S</u> <u>14</u>	<u>SW</u> <u>116S</u> <u>14</u>		
<u>BT</u>	<u>BT</u>		

Species W. Pine Maple

Diameter 10" 9"

Bearing N 85 W S 87 E

Distance 36 lks. 21 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. M. Handy
(Signature)
C. O. P.

(Date)

(Title)

M-18

UNITED STATES GEOLOGICAL SURVEY

WATER RESOURCES DIVISION

REPORT OF INVESTIGATION

NO. 100

WATER RESOURCES DIVISION

UNITED STATES GEOLOGICAL SURVEY

WASHINGTON, D. C.

1950

Corner again.

Give any further facts which will aid in finding this


chain distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. 5th Mer.

1/16 Corner common to Sections
, and 14

Corner consists of a Iron pipe (not) in place
State condition good

Dimensions above ground 1.5 by 12" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

SW 1/16 s14			
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SW 1/16 14	S	SW 1/16 14		
BT		BT		

Species W. Pine Maple

Diameter 10" 9"

Bearing N85W S82E

Distance 36 lks. 21 lks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

E. M. Hardy

(Signature)

Chief of party

(Date)

8-73

Chief

(Title)

M-18

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

M-18

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 5th Mer.

----- SW 1/16 Corner common to Sections
 -----, -----, 14, and -----

Corner consists of a Iron pipe (not) in place
 State condition good

Dimensions above ground 1.5" X 1.2" inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>SW</u>			
<u>416</u>			
<u>S. 14</u>			
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>SW</u>	<u>SW</u>		
<u>416</u>	<u>416</u>		
<u>S. 14</u>	<u>S. 14</u>		
<u>B. T.</u>	<u>B. T.</u>		

Species W. P. Maple
 Diameter 10" 9"
 Bearing N 85 W S 87 E
 Distance 36 lks 21 lks.

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why? -----

C. M. Handy
 (Signature)

Chief of Party
 (Title)

(Date)

M-18

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 144 R. 29 S. 54 M-18 Mer.