

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 29 W. 5 th. Mer.

1/4 Corner common to Sections

14, and 23

Corner consists of ~~astake~~ ~~not found.~~ (not) in place  
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 14
-------------

--

--

--

BT
----

--

--

--

Species Cedar

Diameter 10"

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why?

*E. M. Hardy*

(Signature)


Chief of party

(Date)

(Title)

127.  
 GIO COR. was established in 1926 or  
 dating back to 1912 while the present  
 There are dates on the last mentioned  
 will be attached to this description.  
 does not. The description of this cor.  
 Lewitt Plats while the present cor.  
 checks with the bearings given on the  
 Corner again. (continued)

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree... inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W 5<sup>th</sup> Mer.



1/4 Corner common to Sections  
14, 23, and

Corner consists of a iron stake (not) in place  
State condition

Dimensions above ground 6" inches.  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>S23</u>	<u>1/4</u> <u>S10</u>		
<u>BT</u>	<u>BT</u>		

Species	<u>Cedar</u>	<u>Cedar</u>		
Diameter	<u>4"</u>	<u>12"</u>		
Bearing	<u>S10E</u>	<u>N30E</u>		
Distance	<u>7'</u>	<u>50'</u>		

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why?

*John Brown*

Signature

12/18/30  
Date.

Estimator  
Title.


(Make sketch of topography near Corner.)

N-19 Mer.

Sec. 3

R. 29W

T. 144N



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant

Give any further facts which will aid in finding this

Corner again.

*[Handwritten signature]*