

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. 5<sup>th</sup> Mer.

1/16 Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, and 14

Corner consists of a Iron pipe (not) in place  
 State condition good

Dimensions above ground 1.5" x 12" inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

EC			
1/16			
S 14			
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

CE 1/16	CE 1/16		
S 14	S 14		
B.T.	B.T.		

Species Maple Maple

Diameter 8" 9"

Bearing N 12 W S 88 W

Distance 28 1/2 65 1/2

Do you believe this to be a genuine Land Office Corner? Yes  
 If not, why? \_\_\_\_\_

E. M. Handy  
 (Signature)

C. O. P.  
 (Title)

(Date)



U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. 5 th. Mer.

1/16 Corner common to Sections  
, and 14

Corner consists of a Iron pipe (not) in place  
State condition good

Dimensions above ground 1.5" by 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

ES 17/16 S14			
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

CE1/16 S 14	CE1/16 S 14		
BT	BT		

Species Maple Maple  
 Diameter 8" 9"  
 Bearing N12W S88W  
 Distance 28 lks. 65 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

E. M. Handy  
(Signature)

Chief of party  
(Title)

(Date)



U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

L-20

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14N R. 29 5th Mer.



1/6 Corner common to Sections  
17, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a 1200 Staks-brass cap (not) in place  
State condition good

Dimensions above ground 17 inches.  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	<u>Maple</u>	<u>Maple</u>	_____	_____
Diameter	<u>12'</u>	<u>10'</u>	_____	_____
Bearing	<u>S80W</u>	<u>N13W</u>	_____	_____
Distance	<u>40</u>	<u>20</u>	_____	_____

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_

O. R. Brewer  
Signature.  
Estimator  
Title.

7/17/30  
Date.

L-20

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

*Alou Road*

Corner again.  
 Give any further facts which will aid in finding this  
 ----- chains distant.  
 from which this Corner bears -----  
 side of -----  
 tree ----- inches diameter, on the  
 Metal Location Poster is on a -----

	Sec.		Sec.
	Sec.	♦	Sec.

8-2027 (Make sketch of topography near Corner.)

T 1444 R. 2964  
 Mef. L-20