

Copied & Posted
5/36

U. S. Department of Agriculture
FOREST SERVICE

----- NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer. 5

1/4 Corner common to Sections

-----, -----, 13, and 14
Corner consists of a New Stake (not) in place

State condition -----

Dimensions above ground ----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

(Signature)

(Date)

(Title)

L-21

Handy
Posted

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. 5 Mer.

1/4 Corner common to Sections
13, and 14

Corner consists of a iron pipe (net) in place
State condition good

Dimensions above ground 1.5" by 12" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4			
13			
14			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S14	1/4 S13		
BT	BT		

Species N. Pine N. Pine

Diameter 14" 12"

Bearing N 81W S 78E

Distance 30 Lks. 1 Ch.

Do you believe this to be a genuine Land Office Corner? *yes*
If not, why? _____

E. M. Handy
(Signature)

C. O. P.
(Title)

(Date)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa..... NATIONAL FOREST

P. 123

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. 5 th. Mer.

1/4 Corner common to Sections
13, and 14

Corner consists of a Iron pipe (not) in place
State condition good

Dimensions above ground 1.5" by 12" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4			
13			
14			

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
S 14

1/4
S 13

--

--

BT

BT

--

--

Species N. Pine N. Pine

Diameter 14" 12"

Bearing N81W S78E

Distance 30lks. 1 ch.

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

E. M. Handy

(Signature)

Chief of party

(Date)

(Title)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144 R. 39 5th Mer.

1/4 Corner common to Sections
12, and 14

Corner consists of a IRON PIPE (not) in place
State condition good

Dimensions above ground 1.5" X 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>			
<u>12</u>			
<u>14</u>			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
S 14

1/4
S 13

B.T.

B.T.

Species N.P. N.P.

Diameter 1.4" 1.2"

Bearing N 81 W S 78 E

Distance 30 lks. 1 ch.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

C. M. Handy

(Signature)


Chief of Party

(Title)

(Date)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)