

U. S. Department of Agriculture
FOREST SERVICE

123

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 29 W Mer.

114 Corner common to Sections

1, and 12
Corner consists of a IRON PIPE WITH BRASS CAP in place

State condition good AND CEDAR STAKE

Dimensions above ground 4" square 4" high

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
S		S	
1		12	

S			
4 3/4			
12			

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____
 Diameter _____
 Bearing _____
 Distance _____

No B.T.

Do you believe this to be a genuine Land Office Corner? Yes,
If not, why? _____

HANSON
(Signature)

12/5/36
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

10 LINKS distant.

552. W

from which this Corner bears

side of


Tree

tree 3 inches diameter, on the

S.W

Metal Location Poster is on a

10 W



(Make sketch of topography near Corner)

Mer.

E-23

T. 144 N. R. 29 W.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

already posted

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W Mer.

1/4 Corner common to Sections

_____, _____, 1, and 12
 Corner consists of a iron pipe with brass cap (not) in place
 State condition good and cedar stake

Dimensions above ground 4" square 4" high

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>5</u>	<u>5</u>	<u>5</u>	
<u>1</u>		<u>12</u>	
N	W	S	E

DIAGONAL POSITION

	<u>151</u>		
	<u>4512</u>		
	<u>1935</u>		
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____ No. B.Y.

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Hanson
 (Signature)

12/5/36
 (Date)

(Title) E-23

Corner again.

Give any further facts which will aid in finding this

10.11 mi. bearing distant.


from which this Corner bears 3 52. M.

side of Tree

tree 3 inches diameter, on the

Metal Location Poster is on a

14.11 mi.



(Make sketch of topography near Corner)

T. 144 N. R. 29 W. Mer.

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W 5th Mer.

1/4 Corner common to Sections

1, 8, 12, and _____

Corner consists of a Post with bearing (not) in place

State condition Good

Dimensions above ground 12 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1		12	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

✓	✓		

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? _____

1/8/31
Date.

A. P. Brewer
Signature.
Estimator
Title. E-23-3027

(Make sketch of topography near Corner.)

T. 121N R. 20W 5th Mer.



Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

chains distant.

Give any further facts which will aid in finding this

Corner again.

By Order of