

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 24 E. 5th Mer.

Sec. 1st. Corner common to Sections

1, 12, 6, and 11

Corner consists of a not in place (not) in place

State condition —

Dimensions above ground — inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

31			
N	W	S	E

36	1	6	31
NW	SW	SE	NE

Mound of — is located —

Pits are located —

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T125N
1028W
Sec 6

T125N
1279W
Sec 100

BT

BT

Species 1 Pine 1 Pine

Diameter 13 18

Bearing — N 66 W

Distance ✓ ✓

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? —

P. R. Boerner

Signature

Estimator


1/1/31

Date.

Title. A-25 3027

T. 14441414 R. 29028 W. 5 Mer.

8-3027 (Make sketch of topography near Corner.)



Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

_____ chains distant.

Give any further facts which will aid in finding this

Corner again

In bunch of old tree (see)