

U. S. Department of Agriculture  
FOREST SERVICE

Posted V1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 30W. 5th Mer.



Lot Corner common to Sections  
31, and 30

Corner consists of a Bc Cap. 1" iron pipe in place  
State condition good

Dimensions above ground 2 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Nine

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

Dorman J. Sutton  
(Signature)

8-31-34  
(Date)


Compassman  
(Title)



Diagram

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 144N R. 30W 5 Mer. V-1