

U. S. Department of Agriculture
FOREST SERVICE

posted
N1

Supplement NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 1441 R. 3043 Mer.

Corner common to Sections

13, 24, 18, and 19

Corner consists of a Iron pipe (not) in place

State condition Good

Dimensions above ground 9 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<u>813</u>	<u>824</u>	<u>835</u>	<u>846</u>
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>7114</u>			
<u>10310</u>			

Species Norway Spruce

Diameter 12"

Bearing N 65° E


Distance 2.67 ch

Do you believe this to be a genuine Land Office Corner?

If not, why?

 (Signature)

 (Date) (Title)



(Make sketch of topography near Corner)

T 144 N. R. 34 W. S. 27 Mer. N-1

Metal Location Poster is on a tree 7 inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.