

L-1

U. S. Department of Agriculture
FOREST SERVICE

Coated

Chippewa NATIONAL FOREST

L1

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 30W & 31W 5th Mer.

1/4 Corner common to Sections
18, and 19

Corner consists of a Be-Caped 1" (not) in place
State condition good

Dimensions above ground 6" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
S13

1/4
S18

B.T.

B.T.

Species S. Pine Aspen

Diameter 6" 6"

Bearing S89°15'W N60°15'E

Distance 30 5 1/4

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Wm. B. Rose

(Signature)

compassman

(Title)

8/30/34
(Date)

L-1



Corner again.

Give any further facts which will aid in finding this


5 1/4
1/2
equals distant.

from which this Corner bears S60°15'W

side of The Lake.

tree 6" inches diameter, on the S West

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 149 N. R. 30431 W. 5 1/4 Mer. 1-1