

U. S. Department of Agriculture
FOREST SERVICE

G-1
Pated
61

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. *144N.* R. *31W.* S. *5th* Mer.

Quarter Corner common to Sections
12, and *7*

Corner consists of a *Brass Caped Pipe (not)* in place
State condition *Good*


Dimensions above ground *10* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *J. Pine N. Pine*

Diameter *7" 18"*

Bearing *N. 39° E. S. 50° W.*

US Distance *30 1/2 38*

Do you believe this to be a genuine Land Office Corner? *Yes*
If not, why? _____

J. A. Gjelhaug

(Signature)

Tech. Eng.

(Title)

9/6/34
(Date)

G-1

