

U. S. Department of Agriculture

FOREST SERVICE

posted

Chipp

NATIONAL FOREST

E1

CORNERS OF THE PUBLIC SURVEY

T. *144* N. R. *30 W* Sec. *5* Mer.

Corner common to Sections *5, 6, 12, and 7*

Corner consists of a *1 pipe, B.C. cap* (not) in place
State condition *Good*

Dimensions above ground *15"* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>T144N</i>			
<i>R30W</i>	<i>R30W</i>		
<i>S1</i>	<i>S.6</i>		
<i>S12</i>	<i>S.7</i>		
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>T144N</i>
<i>R30W</i>
<i>S7</i>

<i>T144N</i>
<i>R31W</i>
<i>S12</i>

<i>BT</i>

<i>BT</i>

--

--

Species *W Birch* *Tamar.*

Diameter *11"* *5"*

Bearing *S53E* *S76W*

Distance *70'* *210'*

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Paul J. [Signature]

(Signature)

Estimator

10/30/31


(Date)

(Title)

1. South East side of open
Trough Swamp
87th Ch to N. and East
Sec. Cor.

Corner again.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 144 N R. 30 W
E-1 Mer. 5