

U. S. Department of Agriculture  
FOREST SERVICE

*Posted*

*Chippewa* NATIONAL FOREST

W3

CORNERS OF THE PUBLIC SURVEY


T. 144 N. R. 30 W. 5<sup>th</sup> Mer.

*Sixteenth #4* Corner common to Sections  
*91*, and

Corner consists of a *Br. cap. 1" iron pipe* in place  
State condition *good*

Dimensions above ground *3"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION                      DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/2</i> <i>S. 91</i>			
<i>BT.</i>			

Species *Birch*

Diameter *6"*

Bearing *N. 83° W.*

Distance *11 1/2*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Dorman J. Sutton*  
(Signature)

*9-6-34*  
(Date)

*Compass 1790*  
(Title)

-----

-----

-----

-----

-----

-----

-----


-----

-----

-----

Corner again.

Give any further facts which will aid in finding this  
 ----- chains distant.  
 ----- from which this Corner bears  
 ----- side of  
 ----- inches diameter, on the  
 ----- Metal Location Poster is on a *None*



(Make sketch of topography near Corner)

T. 144N. R. 30W. 6th  
 W-3  
 W-3