

U. S. Department of Agriculture
FOREST SERVICE

Posted V3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144 N* R. *30 W* *5th* Mer.

Quarter Corner common to Sections
30, and *31*

Corner consists of a *Br. capped 1" pipe* (not) in place

State condition *good*

Dimensions above ground *2* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$
S91

$\frac{1}{4}$
S90

BT

Species *Aspen* *Elm*

Diameter *10"* *7"*

Bearing *S94°E* *N19°E*

Distance *55 1/2 lks* *24 1/2 lks*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dorman J. Sutton
(Signature)

8-28-94
(Date)

Compassman
(Title)

