

U. S. Department of Agriculture
FOREST SERVICE

Posted

R5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 30 W 53 Mer.

Section Corner common to Sections
19, 20, 30, and 29.



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 29.	S 19	S 20	S 19	S 29
B.T.	BT	B.T.	BT	BT

Species Dead W Birch B Ash Elm W Birch B Ash

Diameter 14" 6" 4" 12"

Bearing S 16° 15' E N 16° 30' W N 45° 15' E N 16° 30' W S 65° E

Distance 26 1/2 38 1/2 21 1/2 61 1/4 57 3/4

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


Dan B. Rose
(Signature)

5/29/24
(Date)

COMPASSMAN
(Title)



Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 149N R. 30W. S. 5
 R-5