

C-5

U. S. Department of Agriculture
FOREST SERVICE

posted
C5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N.* R. *30W.* *5th* Mer.


Quarter Corner common to Sections
5, and *6*

Corner consists of a *Brass Caped Pipe* (not) in place
State condition *Good*

Dimensions above ground *8* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Ironwood Aspen*

Diameter *5"* *6"*

Bearing *S. 90° E* *S. 45° W.*

LN Distance *9 1/4* *21*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

J. A. Gjelhaug
(Signature)

Tech. Eng.
(Title)

8/21/34
(Date)

C-5

