

G-9

U. S. Department of Agriculture
FOREST SERVICE

Posted

G9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5th Mer.

Quarter Corner common to Sections
8, and 9



Corner consists of a brass capped pipe (not) in place
State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$ S. 9	$\frac{1}{4}$ S 8		
B. T.	B. T.		

Species W. Pine Aspen

Diameter 3 1/2" 8"

Bearing N. 61° 20' E S. 38° 12' W

(4s. Distance 7 1/2 24

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

F. E. Sandberg
(Signature)


10-29-37
(Date)

Const. Foreman
(Title)

G-9

Corner again.

Give any further facts which will aid in finding this
 27 1/2 chains distant.
 from which this Corner bears N. 61° 20' E.
 side of bearing tree.
 tree 14 inches diameter, on the S.W.
 Metal Location Poster is on a W. Pine



(Make sketch of topography near Corner)

T 144 N. R. 30 W. S 4 Mer.

64