

T-11

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5th Mer.

Quarter 28 Corner common to Sections
28, and

Corner consists of a Br. cap iron pipe (1") in place
State condition good

Dimensions above ground 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Q
1/4
S 28

C
1/4
S 28

BT

B. T.

Species Birch Aspen

Diameter 5" 10"

Bearing N 45° E S 64° 45' W

Distance 28 lk 31 lk

Do you believe this to be a genuine Land Office Corner?

If not, why?

Dorman J. Sutton

(Signature)

Compassman

(Title)

10-2-34
(Date)

T-11

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

..... from which this Corner bears $S 14^{\circ} 43' W$

..... side of tree

..... tree 5 inches diameter, on the SW

..... Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. L. H. N. R. 30 W. 5th Mer.