

Q-11

U. S. Department of Agriculture
FOREST SERVICE

Posted Q-11

Shippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 30 W Mer.

S 1/4 on cent. line Corner common to Sections
21, and


Corner consists of a Brass Capped Pipe (not) in place
State condition Good

Dimensions above ground 4 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 1/16	S 1/16		
S 21	S 21		

B.T.	BT		
------	----	--	--

Species White Pine Balsam

Diameter 1 1/2" 6"

Bearing N 2° 45' E S 89° 30' E

Distance 67 2/3 18 1/2

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

C. R. DuBois

(Signature)

COMPARISMAN

(Title)

10-1-34

(Date)

Q11

Corner again.

Give any further facts which will aid in finding this


0.187 chains distant.

from which this Corner bears N 89° 30' W

side of T 15 S

tree 6 inches diameter, on the N W

Metal Location Poster is on a B&W 94M



(Make sketch of topography near Corner)