

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

R-12
 R-13
 Posted

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY



T. 144 N. R. 30 W. 5th Mer.
Sixteenth Corner common to Sections
 _____, _____, 21, and 28.

Corner consists of a brass capped pipe in place
 State condition Good

Dimensions above ground 7" inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>E 76</u>			
<u>S 28</u>			
<u>B.T.</u>			

Species N. Pine

Diameter 22"

Bearing S 11° 45' E

4 Distance 11 1/4

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

F. E. Sandberg
 (Signature)


10-10-34
 (Date)

Const. Foreman
 (Title)

R-12

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 194N. R. 30 W. S. 24 T. 12
 5-24
 R-12
 Meif.