

U. S. Department of Agriculture
FOREST SERVICE

Patented 13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5th Mer.

Sixteenth Corner common to Sections
21, and 22.



Corner consists of a Brass capped pipe. (not) in place
State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION





N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch W. Pine

Diameter 4" 22"

Bearing N 56° 40' W. N 9° 45' E

Distance 20 146

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


F. K. Sandberg
(Signature)

10-17-34
(Date)

Const. Foreman
(Title)

Corner again.

Give any further facts which will aid in finding this
 ----- chains distant.
 ----- from which this Corner bears
 ----- side of
 ----- tree ----- inches diameter, on the
 ----- Metal Location Poster is on a -----



(Make sketch of topography near Corner)

T. 194N. R. 30 W. S. 4

Mer. 13