

U. S. Department of Agriculture
FOREST SERVICE

Rooted

Chippewa NATIONAL FOREST

L13

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 30 W S. 5 Mer.

Corner common to Sections 16, and 15

Corner consists of a Brass Capped Pipe (not) in place
State condition Good

Dimensions above ground 5 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 144 N
R 30 W
S. 16

S. 15

B.T.

B.T.

Species W. OAK W. PINE

Diameter 9" 12"

Bearing S 56° 35' W S 48° E

Distance 9 1/2 5 1/2

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

C. A. Dubois

(Signature)

COMMISSIONER

(Title)

9-21-34

(Date)

L-13

Corner again.

Give any further facts which will aid in finding this


0.57 chains distant.

from which this Corner bears N 86° E

side of The

tree 6 inches diameter, on the NE

Metal Location Poster is on a Aspen



Make sketch of topography near corner

L-13

R. 30 W