

U. S. Department of Agriculture
FOREST SERVICE

Posted

J13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 30W 512 Mer.

Section Corner common to Sections
9, 10, 16, and 15


Corner consists of a Brass Coped Pipe (not) in place
State condition Good

Dimensions above ground 4 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____, is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 144N.
R. 30W.
910

T. 144N.
R. 30W.
39

516

515

BT

BT

BT

BT

Species Aspen Aspen Elm W. Pine

Diameter 8 6" 13" 15"

Bearing N. 61° E N 55° W S 52° 45' W S. 95° 30' E

Distance 31 1/4 10 132 1/4 206 1/4

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Gedric R. Dubois

(Signature)

Compassman

(Title)

9/20/34
(Date)

Corner again.

Give any further facts which will aid in finding this


..... 0.10 chains distant.

from which this Corner bears S. 55° E.

side of *Trees*

tree 6 inches diameter, on the S. E.

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 199 N. R. 30 W.

57 413 Mer.