

U. S. Department of Agriculture  
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST G13

CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 30W. 5<sup>th</sup> Mer. Quarter  
Corner common to Sections

9, and 10

Corner consists of a Br. cap. iron pipe (not) in place  
State condition good

Dimensions above ground 1" x 9 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

Top CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash Balsam ← Dodd

Diameter 8" 4"

Bearing N65°15'E N42°30'W

Distance 40 7

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Dorman J. Sutton  
(Signature)

10-25-34  
(Date)

Compassman  
(Title)

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

..... *140* from which this Corner bears *S 65° 15' W*

side of *tree*

tree *Ø*..... inches diameter, on the *S W*

Metal Location Poster is on a *ASH*



(Make sketch of topography near Corner)