

P-15

U. S. Department of Agriculture
FOREST SERVICE

Posted P-15

~~Chippewa~~ NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5th Mer.

CENTER QUARTER Corner common to Sections
.....,, and 22



Corner consists of a BROSS SAPPED PIPE (not) in place
State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

#c 1/4
S 22

1/4
S 22

B.T.

B.T.

Species ~~WASP~~ ASPEN

Diameter 1" 10"

Bearing S 16° W. S 36° E.

LKS Distance 32 1/2 43

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

Bryan Lee
(Signature)

Compassman
(Title)

10/18/34
(Date)

P-15

