

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

N15

CORNERS OF THE PUBLIC SURVEY

T. *144N* R. *30W* *5th* Mer.

Quarter Corner common to Sections

15, and *22*

Corner consists of a *Brcap. iron pipe* in place



State condition *good*

Dimensions above ground *1" x 6"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen Aspen*

Diameter *7" 5"*

Bearing *S. 3° W. N 23° 15' W*

Distance *50 lk. 13 lk.*

Do you believe this to be a genuine Land Office Corner? *yes.*

If not, why? _____

Dorman J. Sutton

(Signature)

Compassman

(Title)

10-18-34
(Date)

Corner again.


Give any further facts which will aid in finding this

----- 13 chains distant.

----- from which this Corner bears S 23° 15' E

----- side of tree

----- tree 5" inches diameter, on the S.E. Metal Location Poster is on an Aspen



(Make sketch of topography near Corner)

T. L. HAN R. BAW 5th N-15