

U. S. Department of Agriculture  
FOREST SERVICE

*Posted* ✓/16

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144 N.* R. *30 W.* *5<sup>th</sup>* Mer.


*One sixteenth* Corner common to Sections  
....., and *27*.....

Corner consists of a *Bran capped Pipe* (.....) in place  
State condition *Good*

Dimensions above ground *7* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>15 1/16</i> <i>527</i>	<i>1/16</i> <i>527</i>		
<i>BT</i>	<i>BT</i>		

Species *BIRCH* *ASH* *BIRCH*  
Diameter *14"* *6"* *5"*  
Bearing *Nk°45°E* *S77°20'W* *N 33°E*  
Distance *24 1/2* *39 1/2* *11 1/2*

Do you believe this to be a genuine Land Office Corner? *YES*  
If not, why? .....


*Bryan Lent*  
(Signature)

*10-15-34*  
(Date)

*Comptroller*  
(Title)

Metal Location Poster is on a BIRCH tree 5 inches diameter, on the SW side of TREE from which this Corner bears N33°E 0.11 1/2 chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 144 N. R. 30 W. S. 27  
 Mer. A-16 A-10