

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST L17

CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 30W 5th Mer.

Quarter Corner common to Sections
15, and 14


Corner consists of a *Br. cap. iron pipe* in place
State condition *good*

Dimensions above ground *1" x 9"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *W. Oak Birch*

Diameter *11" 4"*

Bearing *S45°15'E N83°15'W*

Distance *88.1k 28.1k*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Dorman J. Sutton
(Signature)

10-17-34
(Date)

Compassman
(Title)

Corner again.

Give any further facts which will aid in finding this


..... 23 chains distant N 45° 15' W

..... from which this Corner bears ~~N 45° 15' W~~

..... side of tree

..... tree 11" inches diameter, on the N. W.

..... Metal Location Poster is on a W. Oak



(Make sketch of topography near Corner)

T. L. HALL

R. 30W

5TH

1-17