

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

G17

CORNERS OF THE PUBLIC SURVEY

T. *144N.* R. *30W.* *5th* Mer.

Quarter Corner common to Sections

....., *10*, and *11*.....

Corner consists of a *Br. exp. iron pipe* (not) in place

State condition *good*

Dimensions above ground *1" x 9* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Birch W. Spruce*

Diameter *6"* *7 1/2"*

Bearing *N. 46° 15' W. S 64° E*

Distance *94* *85*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Dorman J. Sutton

(Signature)

Compassman

(Title)

10-23-34
(Date)

Faint, illegible text on ruled lines.

Corner again.

Give any further facts which will aid in finding this

chains distant.


34

from which this Corner bears S.W. 1/4 E.

side of tree

tree 6 inches diameter, on the S.E.

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 144 N. R. 90 W. 5th
 5-17 Mer. 5-17