

U. S. Department of Agriculture
FOREST SERVICE

Posted

NATIONAL FOREST

J19

CORNERS OF THE PUBLIC SURVEY

T. *144N* R. *30W* *5th* Mer.


14 Corner common to Sections
11, and *14*

Corner consists of a *Brass red pipe* (not) in place
State condition *Good*

Dimensions above ground *10"* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 144N
R 30W
Sec. 11

SEC. 14

B.T.

B.T.

Species *White Pine W. Pine*

Diameter *7"* *5"*

Bearing *N 77° 45' W* *S 1° 10' W*

Distance *48 1/2* *44 1/4*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

C. R. Dubois
(Signature)

10-23-34
(Date)

COMPRESSMAN
(Title)

Corner again.

Give any further facts which will aid in finding this


..... $0.12\frac{1}{2}$ chains distant.

..... from which this Corner bears $S\ 35^{\circ}E$

..... side of TRAIL

..... tree $6''$ inches diameter, on the $S\ E$

..... Metal Location Poster is on a DARK PINE



(Make sketch of topography near Corner)

T. 194N R. 30W
Mer. J-19