

C-19

Form 874-9—Revised May, 1918

U. S. Department of Agriculture
FOREST SERVICE

Patrol

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N* R. *30W* *5th* Mer.



Quarter Corner common to Sections
2, and

Corner consists of a *Br. cup iron pipe* in place
State condition *good*

Dimensions above ground *1" x 1/2"* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4</i> <i>S 2</i>	<i>1/4</i> <i>S 2</i>		<i>2</i>
<i>B.T.</i>	<i>B.T.</i>		

Species *W. Pine* *W. Pine*

Diameter *11"* *12"*

Bearing *N. 73° 45' E* *N. 22° 45' W*

Distance *22* *8*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dorman J. Sutton
(Signature)

Compassman
(Title)

10-8-34
(Date)

C-19

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

..... from which this Corner bears $57^{\circ}45'W$

side of *tree*

tree 11 inches diameter, on the SW .

Metal Location Poster is on a *W. Pine*



(Make sketch of topography near Corner)

5-19
Met
C-19

5TH

R. 30W

T. 144N