

U. S. Department of Agriculture
FOREST SERVICE

Posted
B-20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 30W 5th Mer.

NE 1/6
2

Corner common to Sections
....., and

Corner consists of a Brass Iron Pipe (not) in place
State condition Good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>T 144N</u> <u>R 30W</u> <u>Sec 2</u>	<u>sec 2</u>		
<u>BT</u>	<u>BT</u>		

Species Cedar Cedar

Diameter 12" 10"

Bearing S 24° 30' E N 28° 20' E

Distance 0.45 0.16

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

C. R. Dubois

(Signature)

Compassman

(Title)

11-9-34

(Date)

Dotted lines for writing.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears 588.20' W

side of Tree

tree 10 inches diameter, on the SW

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T 144 N R 30 W 5-22 B-20 Mer.