

U. S. Department of Agriculture

FOREST SERVICE

~~222~~ **Chippewa** NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. **144 N.** R. **30 W.** S. **5th** Mer.

Corner common to Sections **1**, **2**, **11**, and **12**

Corner consists of a **Metal pipe** (not) in place

State condition **Good Capped**

Dimensions above ground **3"** inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

2	11	12	1
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	8.1		T144N R30W S.1
	B.T.		B.T.

Species **Norway** **Jack Pine**

Diameter **18"** **12"**

Bearing **N36-30 E** **N71W**

Distance **56 Lks.** **96 Lks.**

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

Lloyd Nelson

(Signature)

Nov. 30 1936

(Date)

(Title)

E-21

Corner again.


Give any further facts which will aid in finding this
 ----- chains distant.

----- from which this Corner bears

----- side of

----- tree ----- inches diameter, on the

----- Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Plotted
E21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N.* R. *30W* *5th* Mer.
Section Corner common to Sections
1, *2*, *31*, and *12*

Corner consists of a *Br. cap. iron pipe* (not) in place
State condition *good* *in concrete*

Dimensions above ground *5" x 5* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>T144N</i> <i>R30W</i> <i>S12</i>	<i>S1</i>	<i>SR</i>	<i>S11</i>
<i>BT</i>	<i>BT</i>	<i>BT</i>	<i>B.T.</i>

Species *W. Oak* *N. Pine* *J. Pine* *S. Maple*
 Diameter *4"* *20"* *14"* *7"*
 Bearing *S66°30'E* *N36°30'E* *N70°30'W* *S65°W*
 Distance *174* *56* *97* *137*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Dorman J. Sutton
(Signature)

11-8-34
(Date)

Compassman
(Title)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *S 36° 30' W*

side of *tree*

tree *. 20* inches diameter, on the *SW*

Metal Location Poster is on a *N. Pine*



(Make sketch of topography near Corner)