

U. S. Department of Agriculture
FOREST SERVICE

D-22

~~0113572~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 104 N. R. 30 W. S. 6 1/2 Mer.

SW 1/16

Corner common to Sections

....., and

Corner consists of a Metal pipe (not) in place

State condition Good

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

1	1	1	1

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SW 1/16
S. 1

SW 1/16
S. 1

B. 2.

B. 2.

Species

Cedar

Birch

Diameter

10"

8"

Bearing

N. 27°

S. 25°

Distance

35.5 Lks.

45.5 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Lloyd Tolson

(Signature)

Dec. 2, 1918

(Date)

(Title)

D-22

Corner again.

Give any further facts which will aid in finding this


----- chains distant.

----- from which this Corner bears

----- side of

----- tree ----- inches diameter, on the

----- Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

D22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 30 W. 5th Mer.

SW 1/16 Corner common to Sections

-----, -----, -----, and 1

Corner consists of a Metal Pipe (not) in place

State condition Good

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

1	1	1	1
---	---	---	---

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SW 1/16	
S. 1	

SW 1/16	
S. 1	

B.T.	
------	--

B.T.	
------	--

Species Cedar Birch

Diameter 10" 8"

Bearing N. 9 E. S. 35 E.

Distance 35.5 Lks. 45.5 Lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

Lloyd Folsom

(Signature)


Dec. 2, 1936

(Date)

(Title)

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)