

U. S. Department of Agriculture
FOREST SERVICE

224

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5th Mer.
1 1/16 Corner common to Sections

1, and 36
Corner consists of a Metal Pipe (not) in place
State condition Good

Dimensions above ground 4 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

36		1	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E. 1/16 S. 1	E. 1/16 S. 1		1
B.T.	B.T.		

Species Aspen Aspen
Diameter 10 11
Bearing S 35 W 20 E S 20 E
Distance 73.2 Lks. 61 Lks.

Do you believe this to be a genuine Land Office Corner? Yes
If not, why?


Lloyd Folsom
(Signature)

Dec. 4, 1956
(Date)

Give any further facts which will aid in finding this
 Corner again.

From which this Corner bears
 inches diameter, on the
 side of

Metal Location Poster is on a



(Make sketch of topography near Corner)