

A-24

Form 874-B—Revised May, 1918

U. S. Department of Agriculture
FOREST SERVICE

*clearly
marked*

A24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. S. th. Mer.

1 1/16 Corner common to Sections

1, and 36

Corner consists of a Mental pipe (not) in place

State condition Good

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

36		1	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N 1/16 S.1	N 1/16 S.1		J
B.T.	B.T.		

Species Aspen Aspen

Diameter 10" 11"

Bearing S75 30 E S70 E.

Distance 73.2 lks. 61 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Lloyd Johnson

(Signature)

Dec. 4, 1936


17411

20

(Type P)

A-24

Give any further facts which will aid in finding this
 Corner again;
 from which this Corner bears
 chains distant,
 tree inches diameter, on the
 side of
 Metal Location Poster is on a



(Make sketch of topography near Corner)