

U. S. Department of Agriculture
FOREST SERVICE

posted
V-19-20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144 N* R. *30 W* S. *5* Mer.

Monroe Corner common to Sections

24, and *25*

Corner consists of a *Metal pin* (not) in place


State condition *Good*

Dimensions above ground *10* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of *✓* is located

✓ Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| |
|---------|
| WC MC |
| T 144 N |
| R 30 W |
| S 26 |

| |
|---------|
| WC |
| T 144 N |
| R 30 W |
| S 35 |

| |
|--|
| |
| |
| |
| |

| |
|--|
| |
| |
| |
| |

| |
|------|
| B.T. |
|------|

| |
|------|
| B.T. |
|------|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

Species *ash* *elm*

Diameter *7 1/2"* *6"*

Bearing *N 36° W* *S 42° N*

Distance *45'* *45'*


Do you believe this to be a genuine Land Office Corner?.....

If not, why?

George H. Kyes
(Signature)

Estimator
(Title)

Jan 17, 1931
(Date)



(Make sketch of topography near Corner)

Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

_____ chains distant.

Give any further facts which will aid in finding this

Corner again.

Approx 1 of main from
 north edge of map the
 water gully crosses
 down the middle of the map

T. J. H. W. R. 30 W. 5 Mer.

4-18-30