

X-1-2

U. S. Department of Agriculture
FOREST SERVICE

Posted
X1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY


T. 144N R. 30W Mer. 5th

Lot Corner common to Sections

Corner consists of a Buried pipe 1" (not) in place
State condition 9000

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter No Bearing Trees

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Wm B. Rose

(Signature)

Compassman


(Title)

8/20/39
(Date)

X-1-2



Metal Location Poster is on a *Alone* tree *Alone* inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 144N R. 30W 5th Mer. X-1-2