

V-21

Copied  
dated  
5/36  
V21

Form 874-B—Revised May, 1918

U. S. Department of Agriculture  
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 31 5 Mer.

Corner common to Sections

25, 26, 35, and 36

Corner consists of a old stake (not) in place

State condition

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, lattens, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

(Signature)

(Date)

(Title)

V-21

~~3" diameter about 8" in diam.~~

Corner again.

Give any further facts which will aid in finding this


main dist.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Pester is on a



(Make sketch of topography near Corner)

Mer. 1-21

R.

T.