

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

Posted

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 30 + 31 W 5th Mer.
Section Corner common to Sections

19, 18, 13, and 24

Corner consists of a Br. cap iron pipe (not) in place
State condition good

Dimensions above ground 2 x 8 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species No B. T.'s

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. A. Gjelhaug

(Signature)

2-5-1995

(Date)


Tech. Eng.

by D. J. Sutton

.....
.....
.....
.....
.....
.....
.....
.....

Corner again.

Give any further facts which will aid in finding this
..... chains distant.
..... from which this Corner bears
..... side of
..... tree inches diameter, on the
..... Metal Location Poster is on a



(Make sketch of topography near Corner)

T. L. H. N. R. 31 W. 5th N-25 Mer.
R. 31 W. 5th