

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

Posted

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 31 W 5<sup>th</sup> Mer.

Meander Corner common to Sections 13, \_\_\_\_\_, and \_\_\_\_\_



Corner consists of a GL. O. Br. cap iron in place State condition good

Dimensions above ground 1x6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 13	S 13		
M C	M C		
B T	B T		

Species N. Pine N. Pine

Diameter 9 12

Bearing S 67° E N 75 1/2° E

Distance 19 12

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Dorman J. Sutton

(Signature)

Compassman

(Title)

9-8-34  
(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *No poster*



(Make sketch of topography near Corner)

T. L. HAN R 31W 5th L-23-24 Mer.