

U. S. Department of Agriculture

FOREST SERVICE

T-2

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.

116 Corner common to Sections 30, and

Corner consists of a metal log (rust) in place


State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Four sets of boxes for sketching trees, each consisting of a large square above a smaller rectangle.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? X


If not, why? no evidence

Stanley M. Morrison (Signature)

Forestry and (Title)

9-12-60 (Date)

T. 145 R. 26 Mer. 52



Metal Location Poster is on a Post tree 4 inches diameter, on the Post side of Post from which this Corner bears 0 (Bearing) 0 (Distance) Section line marker between Secs. and is on a Post on the Post (Tree, post, etc.) (Name of road, trail, etc.) located chains 1, W, N, S, from Sec. Cor.; 1/2 Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again:

Bls for Poster N. E. of
Corner - also old Post of
near corner Post direction

