

U. S. Department of Agriculture
FOREST SERVICE

X-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.

1/4 Corner common to Sections
31, _____, and _____

Corner consists of a spruce stake (set) in place


State condition rotted off & lying on ground

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? no evidence

Stanley M. Morrison
(Signature)

9-18-60
(Date)

Forestry aid
(Title)

T. 175 R. 26 S. 2 Mer.



Metal Location Poster is on a W. Spruce tree 11 inches diameter, on the S. side of the from which

this Corner bears S. 5 1/2 chains. (Bearing) (Distance)

Section line marker between Secs. and is on a

located (Tree, post, etc.) on the (Name of road, trail, etc.) chains 1, W. N. S., from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again: Blue line poster N & W of corner