

U. S. Department of Agriculture

FOREST SERVICE

Chippawa NATIONAL FOREST

2-3

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.

116 Corner common to Sections 31, and

Corner consists of a metal peg (set) in place



State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS




N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? no

If not, why? no evidence

Stanley M. Morrison


(Signature)

Forestry and

(Title)

9-10-60

(Date)



Metal Location Poster is on a *Iron pole* tree 5 inches diameter, on the *N* side of *the* from which

this Corner bears _____ (Bearing) _____ (Distance) Chains.

Section line marker between Secs. _____ and _____ is on _____ on the _____ (Tree, post, etc.) _____ (Name of road, trail, etc.)

located _____ chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again:

Bl. Eng. & Survey
N 75.8 corner by