

U. S. Department of Agriculture

FOREST SERVICE

4-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 S. 2 Mer.

1/4 Corner common to Sections 30, and 31


Corner consists of a metal top (not) in place State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in pits and fill blanks below, giving bearings from Corner to trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? no evidence

Stanley M. Morrison

(Signature)

Forestry and


(Title)

9-10-60

(Date)

T. 145 R. 20 Mer. 522

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *31* *31*

tree *9* inches diameter, on the *North*

side of *the*

this Corner bears *N*° *6*'

(Bearing) (Distance) Chains.

Section line marker between Secs. and is on

a on the (Tree, post, etc.)

(Name of road, trail, etc.)

located chains E., W., N., S., from Sec. Cor.; 1/4 Cor.; Witness Cor.

(Cross out nonapplicable)

Give any further facts needed to find Corner again:

Blue line poster to U.S.A.S.
of the corner on 8110
of the corner on 5. side of
corner corner on 5. side of
corner corner on 5. side of