

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 26W 5th. P. Mer.

Section Corner common to Sections
5, 6, 7, and 8.

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

B.T.			
------	--	--	--

Species Cedar Stump

Diameter 9"

Bearing --

Distance --

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

E.M. Handy
E.M. HANDY

(Signature)

C.O.

(Title)

1-19-40

(Date)


Blazed line crosses Fireway #1 off East Mississippi Rapids Road.
Corner again.

Give any further facts which will aid in finding this chains distant.

from which this Corner bears side of

tree inches diameter, on the

Metal Location Poster is on a None



(Make sketch of topography near Corner)

Form 874-S—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Posted
Marius
E-5

Chippewa NATIONAL FOREST


CORNERS OF THE PUBLIC SURVEY

T. 145N R. 26W 5th P. Mer.

Section Corner common to Sections
5, 6, 7, and 8

Corner consists of a _____ (not) in place
State condition _____


Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar Stump

Diameter 0'

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. M. Wandy

(Signature)

C. O. P.


(Title)

1/19/40

(Date)

T. 145 N. R. 26 W. S. 2 P. Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a *W. 1/4*

tree inches diameter, on the

side of

from which this Corner bears

CARDINAL POSITION
obtain distant

Give any further facts which will aid in finding this

Corner again!

Placed line crossed

Finney - 1/4 off East

Mississippi Poplar Rd

CORNER OF THE PUBLIC SURVEY

N. 1/4

WEST SURVEY

U. S. Department of Agriculture
FOREST SERVICE

sent in
12/5/40

E-5



Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 145N R. R6W 5th P Mer.

Section Corner common to Sections
5, 6, 7, and 8

Corner consists of a _____ (not) in place
State condition _____


Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar stump _____

Diameter 94 _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


E. M. Handy
(Signature)
C. O. P.
(Title)

1-19-40
(Date)

U. S. Department of Agriculture

Corner again.
Blazed line crosses
Fire road #1 off East
Mississippi Rapids Rd.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 145 N. R. 36 W. S. 4 P. Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

*Copies
 Pasted
 5-36
 E-5*

NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 146 R. 26 S. 5 Mer.

Corner common to Sections
5, 6, 7, and 8

Corner consists of a no stake (not) in place
 State condition _____

Dimensions above ground _____ inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
 fill blanks below, giving bearings from Corner to Trees and
 Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____


(Signature)

(Date)

(Title)

1. Name of the site
 2. Date
 3. Locality
 4. Name of the person
 5. Name of the institution

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)